

T ECHNICAL INFORMATION



91975

October 2011

(Page 1 of 2)

Subject ▶ Change of Fast charger

For Models ▶ AS1812, BCS540, BCS550, BDA340, BDA341, BDA350, BDA351, BDF343, BDF440, BDF441, BDF442, BDF444, BDF445, BDF446, BDF450, BDF451, BDF451M, BDF452, BDF453, BDF454, BDF456, BFH040, BFH090F, BFL201F, BFL301F, BFL402F, BFR440, BFR450, BFR540, BFR550, BFR750, BFS230, BFS440, BFS441, BFS450, BFS451, BFT041F, BFT082F, BFT124F, BGA400, BGA402, BGA450, BGA452, BGD800, BGD801, BHP343, BHP440, BHP441, BHP442, BHP444, BHP446, BHP450, BHP451, BHP452, BHP453, BHP454, BHP456, BHR162, BHR202, BHR241, BHS630, BJR141, BJR181, BJR182, BJS100, BJS101, BJS130, BJS160, BJS161, BJV140, BJV180, BKP140, BKP180, BLS713, BPB180, BPT350, BSC100, BSC101, BSS500, BSS501, BSS540, BSS610, BSS611, BST110, BST120, BST220, BST221, BST420, BTD061, BTD120, BTD123, BTD124, BTD130, BTD131, BTD132, BTD133, BTD135, BTD140, BTD141, BTD142, BTD144, BTD145, BTD150, BTL060, BTL061, BTL062, BTL063, BTP130, BTP140, BTS130, BTW120, BTW121, BTW150, BTW151, BTW152, BTW153, BTW250, BTW251, BTW450, BUB142, BUB182, BUC121, BUC122, BVC340, BVC350, BVF104, BVF154, BVR340, BVR350, BVR440, BVR450, BVR850, DK1140, DK1142, DK1400, DK1420, DK1445, DK1446, DK1802, DK1804, DK1805, DK1806, DK1816, DK1818, DK1822, DK1826, DK1829, DK1831, DK1833, DK1835, DK1839, DK1852, DK1853, DK1854, DK1855, DK1863, DK1864, DK1866, DK1868, DK1869, DK1871, DK1874, DK1879, KS521D, LC540D, LCT300, LXT227, LXT229, LXT230, LXT231, LXT232, LXT300, LXT301, LXT312, LXT314, LXT315, LXT410, LXT413, LXT418, LXT422, LXT423, LXT424, LXT425, LXT426, LXT427, LXT503, LXT604, SP1815

Country ▶ All countries except Canada, Colombia, Guam, Mexico, Panama, USA (DC18RA for their six countries is still continued for the present time.)

Description ▶ Makita brand DC18RA has been replaced with DC18RC.
Dolmar brand LG-183 has been replaced with LG-184.
The size of the new parts are smaller than that of the current parts.
However, the performance and the charging time remains the same.

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
—	DC18RA fast charger 194335-0	1	←	DC18RC fast charger 195581-8	1	Breazil (127V)
—	DC18RA fast charger 194336-8	1	←	DC18RC fast charger 195582-6	1	Saudi Arabia (127V), Taiwan
—	DC18RA fast charger 194337-6	1	←	DC18RC fast charger 195584-2	1	Austria, Bhutan, Chile, Commonwealth of Dominica, Cyprus, France, Germany, India, Indonesia, Iran, Italy, Netherlands, New Caledonia, Philippines, Poland, Reunion, Russia, Saudi Arabia (220V), South Africa, Spain, Sweden, Switzerland, Tahiti, Thailand, Turkey, Vietnam
—	DC18RA fast charger 194346-5	1	←	DC18RC fast charger 195585-0	1	Austria, France, Germany, Italy, Netherlands, Poland, Reunion, Russia, Spain, Sweden, Switzerland
—	DC18RA fast charger 194338-4	1	←	DC18RC fast charger 195586-8	1	Cyprus, Hong Kong, Kuwait, Malaysia, Singapore, UK (240V)
—	DC18RA fast charger 194345-7	1	←	DC18RC fast charger 195585-0	1	UK (110V)
—	DC18RA fast charger 194339-2	1	←	DC18RC fast charger 195588-4	1	Korea

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
—	DC18RA fast charger 194340-7		1	←	DC18RC fast charger 195589-2		1	Australia, New Zealand
—	DC18RA fast charger 194341-5		1	←	DC18RC fast charger 195590-7		1	Brazil
—	DC18RA fast charger 194342-3		1	←	DC18RC fast charger 195591-5		1	Argentina
—	DC18RA fast charger 194343-1		1	←	DC18RC fast charger 195592-3		1	China
—	DC18RA fast charger 194344-9		1	←	DC18RC fast charger 195593-1		1	UK (110V)
—	DC18RA fast charger set 195486-2		1	←	DC18RC fast charger 195583-4		1	Saudi Arabia (220V)
—	LG-183 fast charger set 194491-6		1	←	LG-184 fast charger set 195594-9		1	France, Germany, Italy, Netherlands, Reunion, Spain
—	Charging circuit 631732-4		1	No	Charging circuit 620066-0		1	Brazil (127V), Saudi Arabia (127V), Taiwan, UK (110V), etc: All 110V-127V countries except Canada, Colombia, Guam, Mexico, Panama, USA Note: The current part remains available until the specifi- cations of DC18RC for North American countries will be set.
—	Charging circuit 631733-2		1	No	Charging circuit 620067-8		1	Argentina, Australia, Austria, Bhutan, Brazil (220V), Chile, China, Commonwealth of Dominica, Cyprus, France, Germany, Hong Kong, India, Indonesia, Iran, Italy, Korea, Kuwait, Malaysia, Netherlands, New Caledonia, New Zealand Philippines, Poland, Reunion, Russia, Saudi Arabia (220V), Singapore, South Africa, Spain, Sweden, Switzerland, Tahiti, Thailand, Turkey, UK, Vietnam
—	Charger case complete 158135-2		1	No	Charger case complete 140824-3		1	All countries except Canada, Colombia, Guam, Mexico, Panama, USA
—	Charger case cover 419567-1		1	No	Charger case cover 452659-3		1	
—	Terminal unit 638493-7		1	←	Terminal unit 638847-8		1	

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

Implementation

From October 2011 MJ, MNC, MKC, MCC, MME and MCA production